

**InspectZero**

InspectZero

AI-Powered Property Inspection Report

Client: Khushi S

Address: Gwalior, Madhya Pradesh, India

Date: 2026-06-18

Defects & Cost (INR)

Location	Description	Severity	Cost (INR)
Wall	Dampness	major	8000

Total Estimated Cost: INR 8,000

Bill of Materials

Item	Qty	Cost (INR)
Waterproofing compound	2 kg	2500
Cement	2 bag	800
Sand	1 unit	600
Paint	4 litres	1500
Labour	2 days	3000

This is an AI-generated estimate. Actual repair costs may vary. Consult a local contractor.