



Client: Pratibha C

Address: Bangalore, Karnataka, India

Date: 2026-06-18

Defects & Cost (INR)

Location	Description	Severity	Cost (INR)
Bedroom Door	Broken wall	major	5000

Total Estimated Cost: INR 5,000

Bill of Materials

Item	Qty	Cost (INR)
Waterproofing compound	1 small piece	150–300
Gypsum board patch (12 mm)	1–2 m	100–300
Metal stud/channel repair	1 roll (partial use)	50–100
Joint tape	2–3 kg	150–300
Jointing compound / POP	1 pc	50–150
Corner bead (if damaged)	0.5 litre	100–200
Primer	0.5–1 litre	200–500
Matching wall paint	Lump sum	50–100
Sandpaper & consumables	1 small piece	150–300
Labor Cost	2 days	2100 - 4000

This is an AI-generated estimate. Actual repair costs may vary. Consult a local contractor.